

Version Info:

1. Minimum FW Version for Update: 1.0.2 Build 20250620 Rel. 41334.
2. Recommended Omada Controller version 5.15 or above.
3. For downloading of any firmware version, please refer to Omada Download Center.

Enhancements:

1. Enhanced wireless channel calibration for improved performance and accuracy.

Bug fixed:

1. Fixed an issue where changing the 6GHz SSID password did not take effect in certain cases.
2. Fixed an issue where RADIUS accounting might not work when connecting MLO clients.

Notes:

1. This version of firmware is applied to the Omada APP 4.24 or above.