

Release Note for ER701-5G-Outdoor (EU) 1.0

Important Notice:

This firmware resolves an issue where WNICs configured for the US region might fail to connect when the Wi-Fi channel is set to “Auto”.

Version Info:

1. Applied Models:

a) ER701-5G-Outdoor (EU) 1.0

2. Firmware Version: 1.0.1 Build 20250910 Rel.69011

3. Minimum FW Version for Update:

a) EU v1.0: 1.0.0 Build 20250826 Rel.68862

For downloading of any firmware version, please refer to [Omada Download Center](#).

4. Recommended Controller Version: 6.0

5. Recommended APP Version: 4.25

New Features:

No.

Enhancements:

No.

Bug Fixed:

1. Fixed an issue where WNICs configured for the US region might fail to associate when the wireless channel was set to “Auto”.

Additional Information:

No.