

Version Info

Firmware for SX3206HPP(UN) 1.20. Recommended Omada Controller V6.0.0.

Enhancements

1. Optimize the stability of the device's adoption status in certain scenarios.
2. Optimize the stability of the spanning tree in certain scenarios.

Bug fixed

1. Fixed the issue of spanning tree anomalies in special scenarios.