

Version Info:

1. Minimum FW Version for Update: 1.6.2 Build 20251107 Rel. 35700.
2. This firmware upgrade is irreversible. Contact Omada technical support if downgrade is required.
3. Recommended Omada Controller version 6.1 or above.
4. For downloading of any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Encrypted the firmware and optimized the algorithm to enhance the overall security of the firmware.

Notes:

1. This version of firmware is applied to the Omada APP v5.1 or above.