

Version Info:

Firmware for S7500-24Y4C(UN) 1.20. Recommended Omada Pro Controller V1.10.20

SHA-256 Value:

fc68763534ac60635e91011e039ccd81449cc96823213582a4a185dc18966d9e

SHA-512 Value:

7acdce339d812c8b28b4d418ee40f789a0b1115df8e72e16c3b5a75d85bdb3da74e3d4266440a69f82178a4edbec5ed2568f40a449ba3378e5339a66f7d1002a

New Features

1. Introducing the new VI of the Omada series, including new logo, Omada domain, theme color etc.
2. Changing the name of the series to Omada Central
3. Removing the default username and password. A username and password need to be manually created after initiating.
4. Changing the default device location to none, default time zone to UTC.
5. The FEC mode is on by default on the uplink ports.

Enhancements

1. Enhanced the stability of stacking system.
2. Enhanced the stability of MLAG system.
3. Enhanced the stability of connection between device and controller.
4. Enhanced the stability of OSPFv3 service.
5. Enhanced the stability of DHCP service.
6. Secured the default password configuration.

Bug fixed

1. Fixed the issue that VLAN trunk features accidentally cause VLAN hardware misconfiguration.

2. Fixed the issue that displayed LAG status mismatch under MLAG scenario.
3. Fixed the issue of a convergence failure when topology changes appear after the stacking system runs for 24.8 days.

Others

This update will enable FEC on uplink ports by default. When you are updating with a MLAG group. Make sure that you update the standby device first before updating the active device, in case the group gets disconnected.