Version Info:

1. Minimum Supported Firmware Version for Upgrade: 2.5.0 Build 250304 Rel.48164n.

Bug Fixes:

1. Fixed the issue where the recording of human and vehicle was occasionally missing in motion recording mode.