

Version Info:

1. Minimum FW Version for Update: 1.3.2 Build 20250901 Rel. 52255.
2. Recommended Omada Controller version 5.15 or above.
3. For downloading of any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Improved device stability.
2. Enhanced device security.
3. Increased client capacity on the 2.4GHz band.

Bug Fixed:

1. Fixed an issue where, when Daylight Saving Time was enabled on the Controller, related configurations might fail to be delivered to the device.
2. Fixed an issue where, with encryption set to WPA2-PSK and MFPR enabled (=1), some AX200 wireless cards failed to associate.
3. Fixed an issue where AX200 wireless cards could not associate to a 5GHz SSID with WPA Personal encryption, WPA mode set to WPA2-PSK/AUTO, and PMF set to Mandatory on the Controller.
4. Fixed an issue where the DUID reported by the device did not contain the device's MAC address and would change after a reboot.

Notes:

1. This version of firmware is applied to the Omada APP v4.24 or above.