

Version Info

Firmware for ES206XPP-M2(UN) 1.0 and 1.6. Recommended Omada Controller V5.15.24.

Enhancements

1. Added a port-based aging mechanism for multicast groups

Bug fixed

1. Fixed an issue related to MMU throughput testing.
2. Fixed an issue where multicast routing ports might occasionally fail to leave multicast groups.
3. Fixed an issue with certain UI display anomalies.