

Release Note for ER706WP-4G(US) v1.20/v1.26

Important Notice:

No.

Version Info:

1. Applied Models:

- a) ER706WP-4G(US) v1.20
- b) ER706WP-4G(US) v1.26

2. Firmware Version: 1.1.10 Build 20260109 Rel.59943

3. Minimum FW Version for Update:

- a) US v1.20: 1.1.7 Build 20251204 Rel.79746 and above
- b) US v1.26: 1.1.7 Build 20251204 Rel.79746 and above

For downloading of any firmware version, please refer to [Omada Download Center.](#)

4. Recommended Controller Version: 6.1

5. Recommended APP Version: 5.0

New Features:

1. Added IPv6 URL Filtering feature.
2. LAN-to-LAN type ACL supports selecting IP Group for both source and destination.
3. Added IPS/IDS feature.

Enhancements:

No.

Bug Fixed:

1. Fixed the issue that configuring WAN Alias causes SD-WAN disconnection.
2. Fixed the issue that abnormal Switch chips cause device malfunction.

- 3. Fixed the issue that DPI cannot intercept http3 traffic.
- 4. Fixed the issue that the SSID cannot be connected after simultaneously enabling MAC and portal authentication.

Additional Information:

No.