

Version Info

Firmware for SG6428XHP(UN) 1.20. Recommended Omada Controller V6.0.0.

SHA-256

f3933fb0716d9894e6a0aa885c9094ee2375a6f77ff3ed41179b63f8d6141fc5

SHA-512

**d7bc09844722424d68e41efb8c5339f267d8f2b066b235b8704cc9fd3351b840b9922
cbf509ba2ba892f7986a5d54d4fa21c31ab30edb0f764259b6c57f9bdf0**

New features

1. Add support for configuring ports in 1G Auto mode.
2. Disabled the ping check function of the DHCP Server by default.

Enhancements

1. Optimized the performance of DHCP Relay.

Bug fixed

1. Fixed an issue where the device could fail to correctly connect to Omada Central after the hostname was modified.
2. Fixed an issue where MAC address flapping might occur when LLDP is enabled on ports in the STP blocked state.
3. Fixed an issue where ports with Disable Profile applied could be re-enabled after Force Provision in Controller mode.