

Version Info:

1. **Minimum FW Version for Update: 1.1.6 Build 20251120 Rel. 55776**
2. **This firmware is fully adapted to Omada Controller v5.15.**
3. **For downloading of any firmware version, please refer to [Omada Download Center](#).**

Bug fixed:

1. Fixed an issue that unexpected logs showed in configuration result after adopted to Controller which would disappear after Force provision.

Notes:

1. This version of firmware is applied to the Omada APP v4.25 or above.