

Version Info:

1. Minimum FW Version for Update: 1.1.5 Build 20250928 Rel. 68499
2. This firmware is fully adapted to Omada Controller v5.15.
3. For downloading of any firmware version, please refer to [Omada Download Center](#).

Bug fixed:

1. Fixed an issue that unexpected logs showed in configuration result after adopted to Controller which would disappear after Force provision.

Notes:

1. This version of firmware is applied to the Omada APP v4.25 or above.