

Version Info:

First firmware for S6500-24G4XF(UN) 1.20.

SHA256:

0c23e4285bbaa5439e7541f34c49a680bfa31fedf8398f6b69d178d42173e84b

SHA512:

**ef3011b8164fc0a1a5d15e976912d70472b43fafd4e90c6cae134acb19e9a2066e4863
67dc6097dd231cc3ae93b20dfbb2f24c0bf46c4626683996a85bf17de8**

New Features

1. Introducing the new VI of the Omada series, including new logo, Omada domain, theme color etc.
2. Changing the name of the series to Omada Campus
3. Removing the default username and password. A username and password need to be manually created after initiating.
4. Changing the default device location to none, default time zone to UTC.

Enhancements

1. Enhanced the stability of stacking system.
2. Enhanced the stability of MLAG system.
3. Enhanced the stability of connection between device and controller.
4. Enhanced the stability of OSPFv3 service.
5. Enhanced the stability of DHCP service.
6. Secured the default password configuration.

Bug fixed

1. Fixed the issue that VLAN trunk features accidentally cause VLAN hardware misconfiguration.
2. Fixed the issue that displayed LAG status mismatch under MLAG scenario.

3. Fixed the issue of a convergence failure when topology changes appear after the stacking system runs for 24.8 days.