

Release Note for ER706W (US) v1.0

Important Notice:

No.

Version Info:

1. Applied Models:

- a) ER706W (US) v1.0
- b) ER706W (US) v1.6
- c) ER706W (US) v1.20
- d) ER706W (US) v1.26
- e) ER706W (US) v1.30
- f) ER706W (US) v1.36

2. Firmware Version: 1.2.8 Build 20260127 Rel.10534

3. Minimum FW Version for Update:

- a) US v1.0/v1.6/v1.20/v1.26: 1.2.1 Build 20250821 Rel.80909 and above
- b) US v1.30/v1.36: 1.2.2 Build 20250928 Rel.80480 and above

For downloading of any firmware version, please refer to [Omada Download Center](#).

4. Recommended Controller Version: 6.1

5. Recommended APP Version: 5.0

New Features:

- 1. Add support for IPv6 URL Filtering
- 2. Add support for selecting IP Group when configuring LAN to LAN ACL.

Enhancements:

No.

Bug Fixed:

1. Fixed the issue that SD-WAN disconnection caused by WAN Alias configuration.
2. Fixed the issue that device forward abnormalities under specific scenarios.
3. Fixed the issue that DPI could not intercept HTTP3 traffic.
4. Fixed the issue that client unable to connect to SSID while enabling MAB and Portal Authentication at the same time.

Additional Information:

No.