

Version Info

Firmware for SG2210P(UN) 5.30 and 5.36, SG2210P(BR) 5.36, SG2210P(EU) 5.36, SG2210P(IN) 5.38. Recommended Omada Controller V6.0.0.

Bug fixed

1. Fixed the issue of IP loss caused by repeated modification of VLAN configuration by the controller.
2. Fixed HTTP JSON data memory leak issue.
3. Fixed web reset failure issue.