

Version Info:

Firmware for SG2218(UN) 1.30, SG2218(UN) 1.36. Recommended Omada Controller V6.0.0.

Bug fixed

1. Fix the issue of IP loss caused by repeated modification of VLAN configuration by the controller.
2. Fix httpJson memory leak issue