

Version Info:

Firmware for SG3428XF(UN) 1.30, SG3428XF(UN) 1.36, SG3428XF(IN) 1.38.

Recommended Omada Controller V6.0.0.

Bug fixed

1. Fixed the issue of IP loss caused by repeated modification of VLAN configuration by the controller.
2. Fixed httpJson memory leak issue
3. OAM oui modification.
4. lldp-med function Country Code modification.