

Version Info:

Firmware for SG3452(UN)1.30/1.36, SG3452(IN)1.38. Recommended Omada Controller V6.0.0.

Bug fixed

1. Fix the issue of IP loss caused by repeated modification of VLAN configuration by the controller.
2. Fix httpJson memory leak issue