

Version Info:

1. Minimum FW Version for Update: 1.0.0 Build 20250827 Rel. 67870.
2. Recommended Omada Controller version 5.15 or above.
3. For downloading of any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Optimized daylight-saving time feature.

Bug fixed:

1. Fixed an issue where the device might fail to be configured and require manual force provisioning.
2. Fixed an issue where the configured channel might does not match the channel the device is actually using.
3. Fixed an issue where the client AP's automatic adoption might fail.

Notes:

1. This version of firmware is applied to the Omada APP v4.25 or above.