

Version Info:

Firmware for SX3832MPP(UN) 1.20,SX3832MPP(UN) 1.26. Recommended Omada Controller V6.0.0.

Bug fixed

1. Fixed HTTP JSON memory leak issue.
2. Fixed web reset failure issue.
- 3.Fixed the abnormal issue of POE schedule function in the force provision phase.