

Version Info:

1. Minimum FW Version for Update: 1.0.1 Build 20250318 Rel. 84701.
2. This firmware upgrade is irreversible. Contact Omada technical support if downgrade is required.
3. This firmware is fully adapted to Omada Controller 5.15.
4. For downloading of any firmware version, please refer to Omada Download Center.

New Features:

1. Added Support for Multiple Bridge Auto-Pairing.

Enhancements:

1. Enhanced network security.

Notes:

1. This version of firmware is applied to the Omada APP 4.23 or above.