

#### Version Info:

1. Minimum FW Version for Update: 1.1.2 Build 20250901 Rel. 74897
2. This firmware upgrade is irreversible. Contact Omada technical support if downgrade is required.
3. This firmware is fully adapted to Omada Controller 5.15 and above
4. For downloading of any firmware version, please refer to [Omada Download Center](#).

#### Enhancements:

1. Encrypted the firmware to improve overall firmware security.

#### Bug fixed:

1. Fixed an issue where Wi-Fi 7 APs reported significantly fewer logs to the syslog server compared to Wi-Fi 6 APs.
2. Fixed an issue where full configuration push failed in certain scenarios, causing deletion of device SSIDs, profiles, backup node information for cluster adoption, etc.
3. Fixed a hidden issue in the mesh code.
4. Fixed a memory leak caused by retrieving CA certificates from the cloud.
5. Fixed an issue where the last 48 bits of the UUID sent during DHCPv6 dialing were zero.
6. Fixed an issue where, under WPA3 + 802.11r, normal roaming between different bands on the same AP failed.
7. Fixed an issue where syslog server received no logs after VLAN was enabled on a Wi-Fi 7 AP.
8. Fixed an issue where, under PPSK with RADIUS unbound MAC configuration, mandatory PMF caused client association failure.

#### Notes:

1. This version of firmware is applied to the Omada APP 4.24 or above.