

Version Info

1. Minimum FW Version for Update: 1.0.0 Build 20251010 Rel. 76125.
2. Recommended Omada Controller version: 6.2 or above.
3. For downloading of any firmware version, please refer to [Omada Download Center](#).

New Features

1. Added Support for the Omada Config tool to batch configuration of Omada devices.
2. Added Support for portal authentication/deauthentication buttons to the client list in the web interface.
3. Added Support for CLI commands to support iPerf3 speed tests.
4. Added Support for brute-force attack prevention for AP adoption via the controller.
5. Added Support for the Load Balancing feature.
6. Added Support for the 6 GHz PPSK feature.
7. Added Support for the time window setting for Adaptive WLAN Optimization.
8. Added Support for the Wi-Fi Calling feature.
9. Added Support for the NAT Traversal feature.

Enhancements

1. Optimized device cloud upgrade timeout scenarios, supporting Breakpoint Resume functionality.
2. Optimized AP LAN port status display on the controller.
3. Optimized system stability.
4. Optimized the client list display on the web interface, adding the guest client list.
5. Adjusted the Band Steering function to only apply to the SSID level.

Bugs Fixed

1. Fixed the issue where the ACL allow list for inter-terminal communication was not effective when guest networks were enabled.
2. Fixed topology display anomalies in some scenarios.
3. Fixed anomalies in data statistics for certain wired scenarios.
4. Fixed the issue where guest clients could not access the portal logout page.
5. Fixed the issue where wired terminals still appeared online after being offline for 5 minutes.
6. Fixed the issue where PPSK configuration changes did not take effect promptly on controllers earlier than V5.14.

Notes:

1. This version of firmware is applied to the Omada APP v5.2.6 (iOS) and v5.2.19 (Android).