

#### Version Info:

1. Minimum FW Version for Update: 1.1.2 Build 20250901 Rel. 74897.
2. Recommended Omada Controller version 5.15 or above.
3. For downloading of any firmware version, please refer to [Omada Download Center](#).

#### Enhancements:

1. Optimized cloud firmware detection and upgrade mechanism.
2. Optimized DFS mechanism.
3. Optimized CLI commands.

#### Bug fixed:

1. Fixed an issue where the device might fail to upgrade.
2. Fixed an issue where the device might experience a memory leak under certain circumstances.
3. Fixed an issue where the bandwidth might be displayed incorrectly under certain circumstances.
4. Fixed an issue where MLO client information might be displayed incorrectly.

#### Notes:

1. This version of firmware is applied to the Omada APP v4.24 or above.