

Version Info:

1. Minimum FW Version for Update: 1.3.2 Build 20250901 Rel. 52255.
2. This firmware upgrade is irreversible. Contact Omada technical support if downgrade is required.
3. Recommended Omada Controller version 5.15 or above.
4. For downloading of any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Encrypted the firmware and optimized the algorithm to enhance the overall security of the firmware.
2. Improved the client capacity of single device.
3. Improved system stability.
4. Improved usability of AFC feature.

Bug fixed:

1. Fixed the issue where certain devices could not connect.
2. Fixed the issue where power was transmitted abnormally in the 2.4 GHz band under specific power bandwidth.
3. Fixed the issue where scanning 5 GHz neighboring SSID information might fail.
4. Fixed the issue where, in repeater mode, setting a specific channel on 6GHz band might fail after refreshing.
5. Fixed the issue where disabling AFC could cause the SSID to become undeletable and render the 2.4 GHz and 5 GHz radios unavailable.
6. Fixed the issue where adding an SSID with OWE encryption through Omada APP might cause the web interface to display two SSIDs on the 6 GHz band.

Notes:

1. This version of firmware is applied to the Omada APP v4.24 or above.