

Version Info:

1. Minimum FW Version for Update: 1.1.2 Build 20250901 Rel. 74897.
2. Recommended Omada Controller version 5.15 or above.
3. For downloading of any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Encrypted the firmware and optimized the algorithm to enhance the overall security of the firmware.
2. Optimized log reporting to the syslog server.
3. Optimized roaming mechanism.
4. Optimized daylight-saving time (DST) mechanism.
5. Optimized PMF mechanism.
6. Enhanced mesh link stability.
7. Optimized SSID addition mechanism.

Bug fixed:

1. Fixed an issue where the device might reboot unexpectedly.
2. Fixed an issue where mandatory PMF could cause client association failure when PPSK with RADIUS unbound MAC is configured.
3. Fixed an issue where the configuration failed to be delivered to the device after creating and enabling a new entry in IoT Transport Streams.

Notes:

1. This version of firmware is applied to the Omada APP 4.24 or above.