

Version Info:

1. Minimum FW Version for Update: 1.1.2 Build 20250901 Rel. 74897.
2. This firmware upgrade is irreversible. Contact Omada technical support if downgrade is required.
3. Recommended Omada Controller version 5.15 or above.
4. For downloading of any firmware version, please refer to Omada Download Center.

Enhancements:

1. Encrypted the firmware and optimized the algorithm to enhance the overall security of the firmware.

Bug fixed:

1. Fixed an issue where the log content reported by devices to the syslog server was incomplete.
2. Fixed an issue where configuration delivery might fail in Controller mode.
3. Fixed an issue where fetching CA certificates from the cloud might cause memory leaks.
4. Fixed an issue where an abnormal DUID was sent during DHCPv6 dial-up.
5. Fixed an issue where clients might fail to roam between different frequency bands of the same device when using WPA3 encryption with 802.11r enabled.
6. Fixed an issue in Controller mode where Daylight Saving Time ended prematurely.
7. Fixed an issue in Controller mode where Daylight Saving Time configurations might fail to be applied.
8. Fixed an issue in APP-managed devices where adding a tri-band SSID with OWE encryption caused abnormal display of the 6GHz band on the web interface.
9. Fixed an issue in Standalone mode where the "get source IP" function for SNMP failed to take effect.
10. Fixed an issue in Controller mode where creating a new WPA Personal encrypted 5GHz/2.4GHz SSID with certain configurations caused some clients to fail association.

Note:

1. This version of firmware is applied to the Omada APP 4.24 or above.