

Version Info:

1. Minimum FW Version for Update: 1.2.7 Build 20251114 Rel. 38779.
2. This firmware upgrade is irreversible. Contact Omada technical support if downgrade is required.
3. Recommended Omada Controller version 6.0 or above.
4. For downloading of any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Enhanced security.

Bug fixed:

1. Fixed an issue where accounting might be abnormal after roaming when using PPSK with RADIUS bound MAC encryption.
2. Fixed an issue where the device might disconnect in certain scenarios.
3. Fixed an issue where the device might experience a memory leak when the network is unstable.

Notes:

1. This version of firmware is applied to the Omada APP v5.0 or above