

Release Note

Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

- 1. Firmware Version:** 1.0.2 Build 20260507 Rel. 10534
- 2. Applied Model:** EAP727 1.0
- 3. Minimum FW Version for Update:** 1.0.0 Build 20260105 Rel. 76630.
- 4. Recommended Omada Controller version:** 6.1.0.11.
- 5. Recommended Omada App version:** 5.0.3.
6. For downloading any firmware version, please refer to [Omada Download Center](#).

Bug Fixed:

1. Fixed an issue where a memory leak occurred when configuring RadSec.