

Release Note

Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 1.1.9 Build 20260517 Rel. 24459
2. **Applied Model:** EAP787 v1.0
3. **Minimum FW Version for Update:** 1.1.8 Build 20260517 Rel. 24898
4. **Recommended Omada Controller version:** 5.15
5. **Recommended Omada App version:** 4.24
6. For downloading any firmware version, please refer to [Omada Download Center](#)

Enhancements:

1. Encrypted the firmware to improve overall firmware security.

Additional Information:

1. Optimized the RED Certification.