

Version Info:

1. Minimum Supported Firmware Version for Upgrade:
 - a) JP v2.20: 2.1.5 Build 20241216 Rel.65023 and above
 - b) JP v2.30: 2.1.6 Build 20260127 Rel.46840 and above
2. Recommended Controller Version: 6.2
3. Recommended APP Version: No
4. Applied Models:
 - a) ER7206(JP) 2.20
 - b) ER7206(JP) 2.30

New Features

1. Added support for IPv6 dial-up modes including V6plus and DS-Lite.
2. Added support for enhanced DHCP server capabilities, including multi-range address allocation and client list display.
3. Added support for multi-channel configuration.
4. Added integration of a built-in speed test tool.
5. Added support for configurable SIP ALG port.

Enhancements

1. Improved system performance and startup speed.
2. Improved overall system stability and reliability.
3. Enhanced configuration efficiency for network and VPN settings.
4. Improved load balancing functionality and traffic statistics efficiency.
5. Expanded SD-WAN capabilities.

Bug Fixes

1. Fixed some known issues.