

Release Note

Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 3.3.1 Build 20251216 Rel. 63508
2. **Applied Model:** EAP235-Wall(JP) v1.0/1.20
3. **Minimum FW Version for Update:** 3.3.0 Build 20251216 Rel. 54539
4. **Recommended Omada Controller version:** 5.14
5. **Recommended Omada App version:** 4.17
6. For downloading any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Encrypted the firmware and optimized the algorithm to enhance the overall security of the firmware.

Additional Information:

1. Adapted to the RED certification requirement.