

# Release Note

## Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

## Version Info:

1. **Firmware Version:** 1.0.2 Build 20260513 Rel. 12500
2. **Applied Model:** Flex Bridge 5 1.0
3. **Minimum FW Version for Update:** 1.0.0 Build 20260207 Rel. 10726.
4. **Recommended Omada Controller version:** 6.2.
5. **Recommended Omada App version:** 5.1.
6. For downloading any firmware version, please refer to [Omada Download Center](#).

## Bug Fixed:

1. Fixed an issue where PoE icons were not displayed on the controller for ports with PoE out enabled.