

Release Note

Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 1.8.3 Build 20260617 Rel. 36045
2. **Applied Model:** EAP610 4.0
3. **Minimum FW Version for Update:** 1.8.0 Build 20260617 Rel. 33212
4. **Recommended Omada Controller version:** 6.1 or above.
5. **Recommended Omada App version:** 5.1 or above.
6. For downloading any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Encrypted the firmware and optimized the algorithm to enhance the overall security of the firmware.

Additional Information:

1. Adapted to the RED.