

## Release Note

### Version Info:

1. **Firmware Version:** 1.6.7 Build 20260616 Rel. 15384
2. **Applied Model:** EAP655-Wall1.0/1.20
3. **Minimum FW Version for Update:** 1.6.2 Build 20251107 Rel. 35700.
4. **Recommended Omada Controller version:** 6.1.
5. **Recommended Omada App version:** 5.1.
6. For downloading any firmware version, please refer to [Omada Download Center](#).

### Enhancements:

1. Optimized the firmware upgrade mechanism to improve upgrade reliability and stability.
2. Optimized device performance when 802.1X authentication is configured.