

Release Note

Important Notice:

This release includes security enhancements for cloud management. Downgrading to an earlier firmware version may cause cloud authentication, cloud management, or cloud-based firmware upgrade features to become unavailable. If issues occur after a downgrade, please contact technical support.

Version Info:

1. Firmware Version: 1.0.2 Build 20260717 Rel.27544

2. Applied Model:

a) S7500-48Y8C(UN) v1.0

b) S7500-48Y8C(UN) v1.6

3. Minimum FW Version for Update:

a) UN v1.0: 1.0.0 Build 20250916 Rel.60051

b) UN v1.6: 1.0.0 Build 20250916 Rel.60051

4. Recommended Omada Controller version: 6.2.14

5. Recommended Omada App version: N/A

6. For downloading any firmware version, please refer to [Omada Download Center](#).

New Features:

1. Added support for a high-strength password hashing algorithm, improving the security of password data.

Enhancements:

1. Optimized the authentication and configuration delivery mechanisms between the device and Cloud-Based/Local Controller.

2. Optimized the authentication mechanism when devices are initially onboarded to the cloud management platform.

Bug Fixed:

1. Fixed an issue where, in scenarios with a large number of LAG/LACP groups, some member ports occasionally failed to aggregate or became blocked during firmware upgrades or master/backup switchover.

Additional Information:

1. SHA-256 Value:

b196787b13db62bd7b41167bef710ad3ca2bd674bdc1b84dca5dd4cf67a61fd4

2. SHA-512 Value:

1fd79154f3fda0c694ec2d31cd5b7dc76c7c1ca066fad65a19a0d213276caff9ed0
f7258aef0d3ac70a99be69fbd1a2d2612291df4deea77c169037d4150578