

Release Note

Important Notice:

This firmware version does not support downgrade. If a downgrade is required, please contact Omada Technical Support..

Version Info:

1. **Firmware Version: 2.4.5 Build 20260721 Rel. 81048

2. Applied Model:

- a) ER605(UN) v2.0
- b) ER605(UN) v2.20
- c) ER605(UN) v2.26
- d) ER605(UN) v2.30
- e) ER605(UN) v2.36
- f) ER605(UN) v2.6
- g) ER605(IN) v2.28
- h) ER605(IN) v2.38
- i) ER605(IN) v2.8
- j) ER605(BR) v2.36

3. **Recommended Omada Controller version:** 6.2.14

4. **Recommended Omada App version:**

N/A

5. Minimum FW Version for Update:

- a) ER605(UN) v2.0: 2.3.2 Build 20251029 Rel.12727 and above
- b) ER605(UN) v2.20: 2.3.2 Build 20251029 Rel.12727 and above
- c) ER605(UN) v2.26: 2.3.2 Build 20251029 Rel.12727 and above
- d) ER605(UN) v2.30: 2.3.2 Build 20251029 Rel.12727 and above
- e) ER605(UN) v2.36: 2.3.2 Build 20251029 Rel.12727 and above
- f) ER605(UN) v2.6: 2.3.2 Build 20251029 Rel.12727 and above
- g) ER605(IN) v2.28: 2.3.2 Build 20251029 Rel.12727 and above
- h) ER605(IN) v2.38: 2.3.2 Build 20251029 Rel.12727 and above
- i) ER605(IN) v2.8: 2.3.2 Build 20251029 Rel.12727 and above
- j) ER605(BR) v2.36: 2.3.2 Build 20251029 Rel.12727 and above

For downloading of any firmware version, please refer to Omada Download Center.

New Features:

- 1. None

Enhancements:

- 1. None

Bug Fixed:

1. Improved device stability.