

Release Note

Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 1.3.11 Build 20260703 Rel. 16605
2. **Applied Model:** EAP673 v1.0/v1.20
3. **Minimum FW Version for Update:** 1.3.6 Build 20260306 Rel. 14246
4. **Recommended Omada Controller version:** 6.0.
5. **Recommended Omada App version:** 5.0.
6. For downloading any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Optimized firmware security by encrypting firmware images and improving the firmware signature algorithm.

Bug Fixed:

1. Fixed an issue where the device could go offline in certain scenarios after configuring a VLAN ID for an SSID.