

Release Note

Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 1.2.1 Build 20260811 Rel.71880
2. **Applied Model:**
 - a) DR3650v(EU) v1.0
 - b) DR3650v(EU) v1.20
3. **Minimum FW Version for Update:**
 - a) EU v1.0: 1.1.0 Build 20250801 Rel.81737
 - b) EU v1.20: 1.1.1 Build 20250929 Rel.81227
4. **Recommended Omada Controller version:** 6.2.14.
5. **Recommended Omada App version:** 5.3
6. For downloading any firmware version, please refer to [Omada Download Center](#).

Enhancements

1. Improved overall system stability and reliability.

Bug Fixed

1. Fixed an issue where VPN connections could fail when MAC Filtering was enabled in whitelist mode.