

Release Note

Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 1.2.1 Build 20260811 Rel.72892

2. **Applied Model:**

- a) ER7412-M2(UN) v1.0
- b) ER7412-M2(UN) v1.6
- c) ER7412-M2(UN) v1.20
- d) ER7412-M2(UN) v1.26
- e) ER7412-M2(UN) v1.30
- f) ER7412-M2(UN) v1.36

3. **Minimum FW Version for Update:**

- a) UN v1.0: 1.1.0 Build 20251015 Rel.63594
- b) UN v1.6: 1.1.0 Build 20251015 Rel.63594
- c) UN v1.20: 1.1.0 Build 20251015 Rel.63594
- d) UN v1.26: 1.1.0 Build 20251015 Rel.63594
- e) UN v1.30: 1.1.1 Build 20251112 Rel.54883
- f) UN v1.36: 1.1.1 Build 20251112 Rel.54883

4. **Recommended Omada Controller version:** 6.2.14.

5. **Recommended Omada App version:** N/A

6. For downloading any firmware version, please refer to [Omada Download Center](#).

Enhancements

- 1. Improved overall system stability and reliability.

Bug Fixed

- 1. Fixed an issue where VPN connections could fail when MAC Filtering was enabled in whitelist mode.