

Release Note

Version Info:

1. **Firmware Version:** 1.4.5 Build 20260831 Rel.65396
2. **Applied Model:**
 - a) ER8411(UN) v1.0
 - b) ER8411(UN) v1.6
 - c) ER8411(UN) v1.20
 - d) ER8411(UN) v1.26
 - e) ER8411(IN) v1.28
3. **Minimum FW Version for Update:**
 - a) UN v1.0: 1.3.5 Build 20251028 Rel.06811 and above
 - b) UN v1.6: 1.3.5 Build 20251028 Rel.06811 and above
 - c) UN v1.20: 1.3.5 Build 20251028 Rel.06811 and above
 - d) UN v1.26: 1.3.5 Build 20251028 Rel.06811 and above
 - e) IN v1.28: 1.3.5 Build 20251028 Rel.06811 and above
4. **Recommended Omada Controller version:** 6.2.14.
5. **Recommended Omada App version:** N/A.
6. For downloading any firmware version, please refer to [Omada Download Center](#).

Bug Fixed

1. Fixed network connectivity issues in certain scenarios.