



## Release Notes for Omada Controller V5.15.8.2

### 1. Supported Device Models

For device models Omada Software Controller supports, refer to: <https://www.tp-link.com/en/omada-sdn/product-list/>

### 2. New Features:

1. Added support for batch configuration of Port config on Wall Plate EAPs at Devices (EAP) >Ports.

### 3. Enhancements:

1. Optimized the VLAN configuration of Easy Managed Switch. The adopted Easy Managed Switch defaults to All Profile, which supports up to 32 VLANs. If there are over 32 VLANs, the Tagged VLAN could be manually selected.
2. Optimized the LAN profile by removing the Easy Managed Switch Enabled toggle so that all VLANs can be available to Easy Managed Switch.

### 4. Bug Fixed:

1. Fixed bug where exporting voucher only export unused vouchers.

### Notes:

1. This version of the Controller is fully applied to the Omada APP of version 4.20 or above.
2. Easy Managed Switch VLAN optimization is applicable in Omada APP v4.22.
3. Omada SDN Controller can only manage certain devices running the supported firmware. Please confirm that your device is compatible with the SDN Controller.
4. Since version 5.14.32, Omada Software Controller no longer supports upgrade from Controller v4.
5. Since version 5.14.32, Omada Software Controller(Windows) only supports installation on **Windows64-bit** platform.